




Schreibtische der A

Assembly instruction : desk range A

MO_AS-2.pdf
Stand: 2022_05

Seite 1

A-Serie



4x **(A)**




6x **(B)**



500182 M6 x 16

8 x **(C)**



500254 PH 6.3 x 19


2x **(D)**



582330 PH 4.5 x 20


Sie benötigen:

Tools:




SW 4

2x **(1)**




A-Fuss li /re 115242


1x **(2)**




KA08-2




KA12-2



KA16-2




KA18-2



KA20-2


1x **(3)**

PL08 / PL12 / PL16 / PL19/ PL2E



PL**

1



4x **(A)**

