



Montageanleitung : Aufsatz-Container SCA1



Korpus: LSCA1






Sie benötigen folgendes
Werkzeug:






Beschlagbeutel (cabinet fittings)



3x A (5 / 5 mm) 500451	12x B (15 / 19mm) 500360	12x C (325A) 500270	8x D (8 x 30 mm) 500578	4x E 508667	6x F (12mm) 579289	6x G (3,5 x 25mm) 500221
---	---	--	--	----------------------------------	---	---

2x H (268x16x11mm)	3x J 579133	A4 (324 x 240 mm) (h = 55 mm)
------------------------------------	----------------------------------	--







7



8

4x **E**6x **F**

(12mm)

4 x **E**6 x **F**3x **J**